

Rosemary Inn, Wren Cabin (Bldg. No. 373)
Olympic National Park
Barnes Point, Lake Crescent
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-185-G

HABS

WASH

5-POANV,

2G-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA


Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

HABS
WASH
5-POAN.V,
29-

NATIONAL PARK SERVICE
Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY
ARCHITECTURAL DATA FORM

STATE WASHINGTON	COUNTY CLALLAM	TOWN OR VICINITY Approximately 20 miles southwest of Port Angeles
HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn, "Wren" Cabin (Historic Building Inventory)		HABS NO. WA-185-G
SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 378		
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.		
DATE OF CONSTRUCTION (include source) c.1920 (Historic Building Inventory)	ARCHITECT(S) (include source) Builder and Craftsman: John Daum (HRS, 1983)	
SIGNIFICANCE (architectural and historical, include original use of structure) Constructed before 1922, this cabin is one of the earliest sleeping cabins built at Rosemary. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, setting, feeling and association.		
STYLE (if appropriate) Craftsman-style cottage		
MATERIAL OF CONSTRUCTION (include structural systems) Wood-frame construction set on split logs and 6 x 6 posts on stone and concrete piers.		
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Square: 10' x 10'		
EXTERIOR FEATURES OF NOTE 1 story; wood-shingled gable roof with extended eaves and exposed rafter ends; horizontal, split-log siding below with staggered woods shingles above; multi-paned hinged sash; plain fascia and corner boards; off center entry door on west facade.		
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; bevelled tongue-and-groove boards in ceiling; 5" painted horizontal wainscotting with 7" vertical boards above; no bathroom.		
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES Cabin may have been moved from original location (n.d); under rehabilitation (1988)		
PRESENT CONDITION AND USE Fair; Vacant		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 National Register Listing, 1979		
COMPILER, AFFILIATION Gretchen A. Luxenberg, National Park Service	DATE July, 1988	



Wren Building #378